Why Prototype Before You Tool: How Waterjet-Cut Gaskets Reduce Costly Production Mistakes

By Eric Thomas, Adherex Group



Successful gasket manufacturing starts long before the first production run. By validating the design with a prototype before investing in tooling, manufacturers can catch fit, function, and material issues early—saving time, reducing waste, and avoiding expensive tooling revisions.

Why gasket mistakes are expensive

Product recalls damage a company's reputation, both externally and internally, and cause delays and material waste. When it comes to gaskets, taking the extra step of prototyping before investing in tooling can save thousands in recut tool dies and allows for quick testing of different materials for fit and performance.

Gaskets are small components with outsized consequences. A gasket that fails in the field—allowing moisture ingress, leaks, or vibration noise—often surfaces only after a product ships, triggering recalls and warranty claims that damage a company's reputation and waste time and material.

The costs start even earlier. Hard tooling is a significant capital investment, and any change to a gasket's geometry, thickness, or material after the die is cut requires recutting—thousands of dollars and weeks of lost schedule over a dimension that's off by a fraction of a millimeter. Prototyping first is the insurance policy: it allows quick, low-cost testing of materials and geometries while changes are still cheap to make.

Why rapid prototypes matter for gaskets

Fail early and fail often is an adage familiar to those in engineering. The whole point of a prototype is to find the failure before it happens in production. Teams that build testing into the front of the development cycle spend less time reworking designs at the back—and get to market sooner as a result.

Gaskets are especially hard to validate on paper. Properties like compression set, durometer, and adhesive tack can only be approximated on a spec sheet—a drawing confirms a gasket fits a groove, but only a physical part confirms it seals under load and stays bonded over time. That's why prototypes are most valuable when made in the production material: engineers can stress-test them in real-world conditions and trust the results will translate.

Why a 5-axis waterjet cutting is ideal for rapid gasket prototyping

A 5-axis waterjet cutter uses a high-pressure stream of water to cut material directly from a digital file, which makes it well-suited for prototyping. For gaskets with angled sealing surfaces or complex cross-sections, 5-axis cutting is often the only way to prototype a part that closely matches production geometry, so the test data it generates directly informs the tooling decision.

The waterjet can handle dense or stacked materials, such as rubber, neoprene, and foam. No tooling is required. To get started, all that's needed is a CAD drawing, which an operator can quickly convert into the machine code. The waterjet provides fast turnaround, in as little as 24-48 hours, depending on the availability of the needed materials.

Transitioning into a production run

Once the prototype has proven out, moving to production is straightforward. The die gets cut once. Approvals go faster because nobody is arguing over a drawing—the part has already been tested, and it works. The prototype step doesn't slow the project down; it's usually what keeps the project on schedule.

For any team specifying gaskets on a new product, the lesson is simple: the cheapest time to find a problem is before the tooling exists. A 5-axis waterjet prototype is a small investment that protects a much larger one.